



# VEHICLE INSPECTION REPORT

**GU22YTK**

## Audi Q5 45 TFSI Quattro S Line 5dr S Tronic

nama  
GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	15/07/2022	Body Style	Estate	Last service miles	39,640
Year	2022	Keys	1	MOT Due	14/07/2026
Mileage	52,356 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	3		
VIN	WAUZZZF3N2117952	Last service date	12/05/2025		

£90 ADDITIONAL FEE

Last service 12/05/2025 at 39,640 miles- 3 main dealer services. Print

### Tyres

NSF	PIRELLI	6.0mm
NSR	CONTINENTAL	5.0mm
OSF	PIRELLI	6.0mm
OSR	CONTINENTAL	5.0mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Not Thru Paint



2: Bumper Front  
Chipped  
1 To 5



3: Wheel nsf  
Scratched  
Up To 50mm



4: Door nsf  
Dented  
Between 10mm + 30mm



5: Door nsr  
Dented  
Between 10mm + 30mm



6: Qtr Panel nsr  
Dented  
2 Or Less Up To 10mm



7: Wheel nsr  
Scratched  
Up To 50mm



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Tailgate  
 Scratched  
 Over 25mm Thru Paint



10: Door osr  
 Scratched  
 UpTo 25mm Thru Paint



11: Door osf  
 Chipped  
 Edge Chip

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK