

VEHICLE INSPECTION REPORT

GV13GNP

Toyota Yaris 1.4 D-4D TR 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	30/07/2013	Colour	SILVER	Gearbox	MANUAL
Year	2013	VIN	VNKKC3D390A048264	Gears	6
Mileage	40,949 Miles Warranted	Body Style	Hatchback	Doors	5
Fuel Type	Diesel	Keys	2		

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	6.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- ABS
- Central locking
- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing nsf
Poor Previous Repair
Poor Paint



2: Bonnet
Chipped
1 To 5



3: Bumper Front
 Poor Previous Repair
 Poor Paint

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK