

VEHICLE INSPECTION REPORT

GJ73UZE

MG Mg 5 TROPHY

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	TBC

nama
 GRADE
4

Details

Reg. date	06/09/2023	Colour	RED	MOT Due	05/09/2026
Year	2023	VIN	LSJE24098PG017330	Gearbox	AUTOMATIC
Mileage	63,712 Miles Warranted	Body Style	Estate	Gears	1
Fuel Type	Electric	Keys	2		

£90 ADDITIONAL FEE 3 pin charging cable only
 Charging port cover broken off


Tyres

NSF	BUDGET	6.0mm
NSR	CONTINENTAL	5.0mm
OSF	BUDGET	6.0mm
OSR	JOYROAD	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Metallic Paint
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
UpTo 25mm Thru Paint




5: Door nsr
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: A Post ns
Dented
2 Or Less UpTo 10mm



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Wheel osr
Scratched
Up To 50mm




12: Door osr
Chipped
1 To 5



13: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



14: Sill os
Dented
Over 30mm



15: Door osf
Chipped
1 To 5



16: Wheel osf
Scratched
Over 50mm



17: Seat Base Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK