



VEHICLE INSPECTION REPORT

GU22XYR

Mercedes-Benz B Class B200 AMG Line Premium Edition 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	19/03/2022	Body Style	MPV	Last service miles	21,224
Year	2022	Keys	2	MOT Due	10/02/2027
Mileage	21,458 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	4		
VIN	W1K2470872J380828	Last service date	11/02/2026		

£90 ADDITIONAL FEE

Last service 11/02/2026 at 21,224 miles- 4 main dealer services. Print

Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Tailgate
Scratched
UpTo 25mm Thru Paint



3: Door nsr
Dented
2 Or Less UpTo 10mm



4: Door nsr
Scratched
UpTo 25mm Thru Paint



5: Wing nsf
Chipped
1 To 5



6: Wheel nsf
Scratched
Over 50mm



7: Bumper Front
Chipped
Multiple Chips



8: Bumper Front
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK