

VEHICLE INSPECTION REPORT

DE13VWN

Skoda Superb 2.0 TDI CR 170 Elegance 5dr DSG

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	15/05/2013	Colour	GREY	MOT Due	21/05/2026
Year	2013	VIN	TMBKF73T9D9048457	Gearbox	SEMI AUTO
Mileage	97,662 Miles Warranted	Body Style	Estate	Gears	6
Fuel Type	Diesel	Keys	2		


Tyres

NSF	BUDGET	Damaged
NSR	SUNNY	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Digital radio
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wing of
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Scratched
UpTo 25mm Thru Paint



7: Door nsr
Chipped
Edge Chip



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Dented
With Paint Damage



11: Qtr Panel osr
Dented
With Paint Damage



12: Wheel osr
Scratched
Over 50mm



13: B Post os
Scratched
Over 25mm Not Thru Paint



14: Door osr
Chipped
1 To 5



15: Door osf
 Scratched
 UpTo 25mm Thru Paint



16: Wheel osf
 Scratched
 Over 50mm



17: Tyre nsf
 Damaged
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK