



VEHICLE INSPECTION REPORT

GP66FGG

Nissan Note 1.2 DiG-S Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	24/12/2016	Body Style	MPV	Last service miles	100,285
Year	2016	Keys	2	MOT Due	23/12/2026
Mileage	106,877 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	7		
VIN	SJNTBAE12U1160345	Last service date	04/09/2025		

Last Service - 4.09.2025 at 100285 miles (7 MAIN DEALER services) High clutch

Tyres


NSF	NEXEN	3.0mm
NSR	BUDGET	5.0mm
OSF	NEXEN	3.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Park assist camera
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Holed
Up To 3mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Bumper Rear
Cracked
Over 25mm




11: Tailgate
Dented
Over 30mm



12: Wheel osr
Scratched
Over 50mm



13: Qtr Panel osr
Dented
With Paint Damage



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Dented
With Paint Damage



16: Wing osf
Scratched
Over 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Seat Back Cover osf
Scuffed
Over 25mm



19: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK