46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

OE10LGZ

Mercedes-Benz B Class B180 BlueEFFICIENCY SE 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	26/07/2010	**Body Style**	MPV	**Last service miles**	101,231
Year	2010	**Keys**	2	**MOT Due**	26/08/2026
Mileage	105,775 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	Petrol	**Service documents**	Printout	**Gears**	5
Colour	SILVER	**Number of stamps**	13		
VIN	WDD2452322J614190	**Last service date**	08/08/2025		

Last service 08/08/2025 at 101231 miles (13 services (1 main dealer). Noisy at idle and suspension knocking

Tyres

NSF	FALKEN	2.0mm
NSR	FALKEN	3.0mm
OSF	FALKEN	2.0mm
OSR	FALKEN	3.0mm
Spare		

Features

- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos

338.1
miles
105775
0 km/h
1724
mph
x1000
1/min

FM
More
100.9 MHz
Radio
Presets
Sound
OK

Condition Check

Damage Photos

1: Bonnet
Dented
With Paint Damage

2: Bumper Front
Poor Previous Repair
Poor Paint

3: Bumper Front
Insecure
Action Required

4: Wheel nsf
Scratched
Over 50mm

5: Wing nsf
Poor Previous Repair
Poor Paint

6: Door nsf
Chipped
Multiple Chips

7: Door nsr
Dented
With Paint Damage

8: Qtr Panel nsr
Dented
With Paint Damage

9: Qtr Panel Moulding ns
Missing
Replace

10: Wheel nsr
Scratched
Over 50mm

11: Bumper Rear
Scratched
Over 100mm Thru Paint

12: Boot Lid
Chipped
Over 5mm

13: Qtr Panel osr
Dented
With Paint Damage

14: Wheel osr
Scratched
Over 50mm

15: Door osr
Dented
Over 30mm

16: Door osf
Poor Previous Repair
Poor Paint

17: Wing osf
Dented
Between 10mm + 30mm

18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK
Airbag light illuminated	OK
ABS light illuminated	OK
Oil warning light illuminated	OK
Service indicator light illuminated	OK

Windows	OK
Radio	OK
Steering	OK