



# VEHICLE INSPECTION REPORT

**RJ18UBR**

## BMW 2 Series 218i Luxury 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	30/06/2018	Body Style	Estate	Last service miles	41,016
Year	2018	Keys	2	MOT Due	11/02/2027
Mileage	44,161 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	5		
VIN	WBA6V72040EM81436	Last service date	30/06/2025		

Last Service - 30.06.2025 at 41016 miles (5 services)

### Tyres

NSF	BUDGET	5.0mm
NSR	RAPID	6.0mm
OSF	BUDGET	5.0mm
OSR	RAPID	6.0mm



### Spare

## Features


- Bluetooth connection
- Telephone
- Towbar
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: A Post ns  
Chipped  
1 To 5



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Tailgate  
Dented  
Between 10mm + 30mm



11: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



12: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



13: Door osr  
Scratched  
Over 25mm Thru Paint



14: Door osf  
Chipped  
Multiple Chips



15: Wheel osf  
Scratched  
Over 50mm



16: Wing osf  
Scratched  
Over 25mm Thru Paint

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK