



VEHICLE INSPECTION REPORT

AY65VWJ

Hyundai I30 1.6 CRDi [136] Premium 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/10/2015	Keys	2	CAP Clean	£3,625.00
Year	2015	Service history	Yes	CAP Average	£3,050.00
Mileage	110,386 Miles Warranted	Service documents	Service Book	CAP Below	£2,525.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	SEMI AUTO
Colour	BLUE	Last service date	29/07/2025	Gears	7
VIN	TMAD351UVGJ302958	Last service miles	99,453	Doors	5
Body Style	Hatchback	MOT Due	09/01/2026		

£65 ADDITIONAL FEE

Last Service - 29.07.2025 at 99453 miles (7 services)

Tyres

NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos






Condition Check




Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osf
Dented
2 Or Less UpTo 10mm



4: Door osr
Dented
Over 2 UpTo 10mm



5: Bumper Rear
Scratched
Over 25mm Not Thru Paint




6: Wheel nsr
Scratched
Over 50mm



7: Wing nsf
Dented
Over 30mm



8: Wheel nsf
Scratched
Over 50mm



9: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK