

# VEHICLE INSPECTION REPORT

**EY68YXD**

## Ford Kuga Vignale 2.0 TDCi 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama  
GRADE  
**2**

### Details

Reg. date	30/09/2018	Colour	BLACK	MOT Due	11/01/2027
Year	2018	VIN	WFOAXXWPMAJM04410	Gearbox	MANUAL
Mileage	99,064 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Diesel	Keys	1	Doors	5

£100 ADDITIONAL FEE

### Tyres

NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Door osf  
Chipped  
1 To 5



2: Door osr  
Chipped  
Edge Chip



3: Door osf  
Chipped  
Edge Chip



4: Door osr  
Scratched  
Over 25mm Not Thru Paint




5: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



6: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



7: Bumper Rear  
Chipped  
Multiple Chips



8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Chipped  
1 To 5



10: Door nsr  
Scratched  
Over 25mm Not Thru Paint



11: Door nsf  
Chipped  
1 To 5



12: Wheel nsf  
Scratched  
Over 50mm



13: Wing nsf  
Chipped  
Multiple Chips



14: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



15: Bumper Front  
Chipped  
Multiple Chips



16: Bonnet  
Chipped  
1 To 5

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK