

VEHICLE INSPECTION REPORT

RK17FTU

DS Ds 3 1.2 PureTech Elegance 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/03/2017	Body Style	Hatchback	Last service miles	65,017
Year	2017	Keys	2	MOT Due	05/02/2027
Mileage	65,077 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREEN	Number of stamps	9	Doors	3
VIN	VF7SAHNZ6HW506505	Last service date	06/02/2026		

Last service 06/02/2026 at 65,017 miles- 9 services (2 main dealer) Book

Tyres


NSF	LAUFENN	5.0mm
NSR	KUMHO	5.0mm
OSF	LAUFENN	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Rusted
Over 5mm



4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Dented
With Paint Damage



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




7: Tailgate
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Qtr Panel osr
Poor Previous Repair
Poor Paint



10: Door osf
Scratched
Over 25mm Thru Paint



11: Wing osf
Chipped
1 To 5



12: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK