

# VEHICLE INSPECTION REPORT

**MT18HXM**

## Peugeot 2008 1.2 PureTech 130 GT Line 5dr

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	30/04/2018	Body Style	Hatchback	Last service miles	49,837
Year	2018	Keys	2	MOT Due	29/04/2026
Mileage	52,107 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	7	Doors	5
VIN	VF3CUHNYMJY064669	Last service date	13/08/2025		

Last Service - 13.08.2025 at 49837 miles (7 main dealer services)

### Tyres

NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	3.0mm
OSR	GOODYEAR	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Telephone
- Fixed panoramic glass roof
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Door osr  
Scratched  
Over 25mm Not Thru Paint



3: Door osf  
Dented  
2 Or Less UpTo 10mm



4: Wheel osr  
Corroded  
Light



5: Tailgate  
Dented  
Over 30mm



6: Bumper Rear  
Chipped  
1 To 5



7: Wheel nsr  
Corroded  
Light



8: Door nsr  
Chipped  
1 To 5



9: Door osf  
Poor Previous Repair  
Rippled UpTo 30%



10: Wing nsf  
Dented  
With Paint Damage



11: Wheel nsf  
Scratched  
Over 50mm



12: Bumper Front  
Scratched  
25 to 100mm Thru Paint



13: Bonnet  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		