



# VEHICLE INSPECTION REPORT

**GY70BXN**

## Peugeot 508 2.0 BlueHDi GT Line 5dr EAT8

nama  
GRADE  
**3**

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |

### Details

|           |                        |                   |            |                    |            |
|-----------|------------------------|-------------------|------------|--------------------|------------|
| Reg. date | 21/09/2020             | Body Style        | Hatchback  | Last service miles | 10,281     |
| Year      | 2020                   | Keys              | 2          | MOT Due            | 15/10/2026 |
| Mileage   | 11,357 Miles Warranted | Service history   | Yes        | Gearbox            | AUTOMATIC  |
| Fuel Type | Diesel                 | Service documents | Printout   | Gears              | 8          |
| Colour    | RED                    | Number of stamps  | 5          | Doors              | 5          |
| VIN       | VR3FHEHYRLY026499      | Last service date | 15/10/2025 |                    |            |

Last Service - 15.10.2025 at 10281 miles (5 main dealer services) Monitoring radar faulty

### Tyres

|       |          |         |
|-------|----------|---------|
| NSF   | MICHELIN | 6.0mm   |
| NSR   | LAUFENN  | 6.0mm   |
| OSF   | MICHELIN | Damaged |
| OSR   | MICHELIN | 6.0mm   |
| Spare |          |         |

## Features


- Bluetooth connection
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Bumper Front Moulding  
Broken  
Replace



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsf  
Chipped  
Edge Chip



7: Door nsr  
Chipped  
1 To 5



8: Wheel nsr  
Scratched  
Up To 50mm

No Image



9: Qtr Panel nsr  
Scratched  
UpTo 25mm Not Thru Paint

10: Bumper Rear  
Scratched  
Up To 25mm Thru Paint

No Image



11: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

12: Door osr  
Chipped  
1 To 5



13: Door osf  
Chipped  
Edge Chip



14: Wheel osf  
Scratched  
Over 50mm



15: Tyre osf  
 Damaged  
 Replace



16: Centre Console Front  
 Scuffed  
 Over 25mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |  |    |
|--------------------------|----|--|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Windows                  | OK | Radio  | OK |
| Sat nav                  | OK | Steering                                       | OK |