



VEHICLE INSPECTION REPORT

CN17NBA

Dacia Duster 1.5 dCi 110 Laureate 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	14/03/2017	Colour	BLUE	MOT Due	08/03/2027
Year	2017	VIN	UU1HSDJ9F57153492	Gearbox	MANUAL
Mileage	77,330 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Diesel	Keys	1	Doors	5

Intermittent issue with driver door handle

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Telephone
- Towbar
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

Photos



Condition Check



Damage Photos



1: Seat Base Cover osf
Holed
UpTo 3mm



2: Seat Base Cover nsr
Holed
UpTo 3mm



3: Bonnet
Poor Previous Repair
Paint Flake



4: Bumper Front
Poor Previous Repair
Poor Paint



5: Wing nsf
Poor Previous Repair
Rippled UpTo 30%



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
Between 10mm + 30mm



9: Door nsr
Chipped
1 To 5



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Dented
Between 10mm + 30mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint




13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osf
Chipped
1 To 5



15: Wing osf
Chipped
1 To 5



16: Roof
Dented
With Paint Damage

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK