

# VEHICLE INSPECTION REPORT

**GY15ZHC**

## BMW X3 xDrive20d SE 5dr Step Auto

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	20/05/2015	Colour	GREY	MOT Due	07/12/2026
Year	2015	VIN	WBAWZ520600K89912	Gearbox	AUTOMATIC
Mileage	39,622 Miles Warranted	Body Style	Estate	Gears	8
Fuel Type	Diesel	Keys	2		

### Tyres

NSF	PIRELLI	Damaged
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Traction control
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Tyre nsf  
Damaged  
Replace



2: Bonnet  
Chipped  
1 To 5



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Door nsf  
Chipped  
1 To 5



5: Door nsr  
Chipped  
1 To 5



6: Door nsf  
Dented  
Over 30mm



7: Wheel nsr  
Scratched  
Over 50mm



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Door osr  
Chipped  
1 To 5



10: Door osf  
Chipped  
1 To 5



11: Screen Front  
Chipped  
UpTo 10mm



12: Wheel osf  
Scratched  
Over 50mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK