



VEHICLE INSPECTION REPORT

GN19OHB

Fiat 500 1.2 Lounge 3dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/05/2019	Body Style	Hatchback	Last service miles	53,498
Year	2019	Keys	2	MOT Due	30/05/2026
Mileage	61,337 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	8	Doors	3
VIN	ZFA312000JB64325	Last service date	06/05/2025		

Last Service - 06.05.2025 at 53498 miles (8 services)

Tyres

NSF	GOODYEAR	4.0mm
NSR	GT RADIAL	5.0mm
OSF	GT RADIAL	4.0mm
OSR	GT RADIAL	5.0mm

Spare

Features


- Bluetooth connection
- Telephone
- Air conditioning
- ABS
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Solid Paint
- Tyre pressure monitor
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



3: Wheel osr
Scratched
Up To 50mm



4: Door nsf
Chipped
Edge Chip



5: Wheel nsf
Scratched
Over 50mm



6: Bumper Front
Scratched
Over 25mm Not Thru Paint



7: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		