



VEHICLE INSPECTION REPORT

HN13MTY

Honda CR-V 2.2 i-DTEC EX 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	14/06/2013	Colour	BROWN	MOT Due	05/08/2026
Year	2013	VIN	SHSRE6790DU004948	Gearbox	MANUAL
Mileage	112,807 Miles Warranted	Body Style	Estate	Gears	6
Fuel Type	Diesel	Keys	2		

Airbag light is on

Tyres

NSF	GOODYEAR	5.0mm
NSR	MICHELIN	5.0mm
OSF	GOODYEAR	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
1 To 5



4: Wheel nsf
Corroded
Light



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5




7: Door nsr
Chipped
1 To 5



8: Roof
Dented
Over 30mm



9: Qtr Panel osr
Chipped
1 To 5



10: Door osr
Scratched
Over 25mm Thru Paint



11: Door osf
Scratched
UpTo 25mm Thru Paint



12: Wheel osf
Corroded
Light

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		