



VEHICLE INSPECTION REPORT

NA70MJE

Audi E-Tron 230kW 50 Quattro 71kWh Technik 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

nama
GRADE
3

Details

Reg. date	06/11/2020	Body Style	Estate	Last service miles	15,894
Year	2020	Keys	2	MOT Due	15/03/2027
Mileage	26,510 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Printout	Gears	1
Colour	BLUE	Number of stamps	1		
VIN	WAUZZZGEXMB004468	Last service date	08/12/2022		

£90 ADDITIONAL FEE.
NO V5

Last service 08/12/2022 at 15,894 miles- 1 main dealer service. Print Intermittent message displays on dash about an electrical fault
2 type 2 charging cables

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm

Spare

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check




Damage Photos




1: Bonnet
Dented
With Paint Damage




2: Bumper Front
Scratched
UpTo 25mm Thru Paint




3: Wing nsf
Scratched
UpTo 25mm Thru Paint




4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




5: Door nsf
Chipped
1 To 5




6: Bumper Rear
Chipped
1 To 5



7: Wheel osr
Scratched
Up To 50mm



8: Door osr
Scratched
Over 25mm Thru Paint



9: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK