

VEHICLE INSPECTION REPORT

MD19FCL

BMW 2 Series 218i Sport 5dr

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	13/05/2019	Colour	GREY	MOT Due	28/10/2026
Year	2019	VIN	WBA6V720005N18966	Gearbox	MANUAL
Mileage	57,290 Miles Warranted	Body Style	Estate	Gears	6
Fuel Type	Petrol	Keys	2		

Sos system failure message displayed

Tyres

NSF	FALKEN	3.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
2 Or Less Up To 10mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Door nsr
Chipped
1 To 5



7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Scratched
Up To 25mm Thru Paint



9: Door osr
Chipped
Edge Chip



10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint



12: Wheel osf
Scratched
Over 50mm



13: Roof
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK