

# VEHICLE INSPECTION REPORT

**GP18BHW**

## Hyundai Tucson 1.6 TGD i Go SE 5dr 2WD

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	31/07/2018	VIN	TMAJ3812LJJ626410	Last service date	08/11/2023
Year	2018	Body Style	Estate	Last service miles	56,250
Mileage	87,322 Miles Warranted	Service history	Yes	MOT Due	30/07/2026
Fuel Type	Petrol	Service documents	Service Book	Gearbox	MANUAL
Colour	BLACK	Number of stamps	6	Gears	6

Last Service - 08.11.2023 at 56250 miles (6 services)

### Tyres

NSF	SUNNY	Illegal
NSR	SUNNY	3.0mm
OSF	SUNNY	Illegal
OSR	SUNNY	4.0mm
Spare		

### Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Chipped  
1 To 5



3: Door osf  
Scratched  
UpTo 25mm Thru Paint



4: Door osf  
Chipped  
1 To 5



5: Door osf  
Chipped  
Edge Chip



6: Door osr  
Chipped  
1 To 5



7: Door osr  
Scratched  
Over 25mm Not Thru Paint



8: Wheel osr  
Corroded  
Light



9: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



10: Bumper Rear  
Chipped  
Multiple Chips



11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



12: Wheel nsr  
Corroded  
Light



13: Qtr Panel nsr  
Chipped  
1 To 5



14: Door nsr  
Chipped  
1 To 5



15: Door nsr  
Scratched  
Over 25mm Not Thru Paint



16: Door nsf  
Chipped  
1 To 5



17: Door nsf  
Scratched  
Over 25mm Not Thru Paint



18: Wing nsf  
Chipped  
Multiple Chips



19: Wheel nsf  
Corroded  
Light



20: Bumper Front  
Chipped  
Multiple Chips



21: Screen Front  
Chipped  
UpTo 10mm



22: Roof  
Poor Previous Repair  
Paint Flake

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK