



VEHICLE INSPECTION REPORT

GK67UEM

Nissan X-Trail 2.0 dCi N-Connecta 5dr 4WD Xtronic [7 Seat]

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	30/09/2017	Colour	SILVER	Gearbox	CVT
Year	2017	VIN		Gears	6
Mileage	95,222 Miles Warranted	Body Style	Estate	Doors	5
Fuel Type	Diesel	Keys	1		

£100 ADDITIONAL FEE Red EML light on car has been plugged in and detects exhaust gas recirculation flow excessive detected
 Oil service due now

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Towbar
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Chipped
Multiple Chips



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Dented
Over 30mm



10: Door osr
Scratched
Over 25mm Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint



12: Wing osf
Chipped
1 To 5



13: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		