

VEHICLE INSPECTION REPORT

GJ710GM

Dacia Sandero Stepway 1.0 TCe Prestige 5dr

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	28/09/2021	Colour	GREY	MOT Due	27/09/2026
Year	2021	VIN	UU1DJF00067858486	Gearbox	MANUAL
Mileage	87,922 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Petrol	Keys	2	Doors	5

£100 ADDITIONAL FEE.

Tyres

NSF	NEXEN	3.0mm
NSR	MICHELIN	4.0mm
OSF	NEXEN	2.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Chipped
Multiple Chips



6: Wheel osr
Scratched
Up To 50mm



7: Qtr Panel nsr
Chipped
1 To 5



8: Bumper Rear
Scratched
25 to 100mm Thru Paint




9: Tailgate
Scratched
Over 25mm Thru Paint



10: Qtr Panel osr
Dented
Over 30mm



11: Door osr
Chipped
1 To 5



12: Door osf
Scratched
Over 25mm Thru Paint



13: Wheel osf
Scratched
Over 50mm



14: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK