



VEHICLE INSPECTION REPORT

GF17UCS

Seat Ateca 1.4 EcoTSI SE 5dr

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	26/05/2017	Body Style	Hatchback	Last service miles	83,765
Year	2017	Keys	2	MOT Due	27/04/2026
Mileage	95,114 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	8	Doors	5
VIN	VSSZZZ5FZH6563016	Last service date	08/04/2025		

Last Service - 08.04.2025 at 83765 miles (8 services)

Tyres

NSF	UNIROYAL	5.0mm
NSR	UNIROYAL	5.0mm
OSF	UNIROYAL	5.0mm
OSR	UNIROYAL	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Screen Front
Chipped
UpTo 10mm



5: Roof
Chipped
Edge Chip



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Scratched
UpTo 25mm Thru Paint



8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osr
Dented
Between 10mm + 30mm



15: Door osr
Chipped
1 To 5



16: Door osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		