

VEHICLE INSPECTION REPORT

GU20KLS

Peugeot 208 100kW Allure 50kWh 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
1

Details

Reg. date	08/06/2020	Colour	GREY	MOT Due	18/06/2026
Year	2020	VIN	VR3UHZKXZLT020339	Gearbox	AUTOMATIC
Mileage	6,355 Miles Warranted	Body Style	Hatchback	Gears	1
Fuel Type	Electric	Keys	2	Doors	5

£100 ADDITIONAL FEE Battery charge fault
Electric traction system fault on dash
Battery light on dash
Drivers window does not work
Type 2 charging cable

Tyres

NSF	FIRESTONE	5.0mm
NSR	FIRESTONE	5.0mm
OSF	FIRESTONE	5.0mm
OSR	FIRESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel nsf
Scratched
Over 50mm



2: Door osr
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
Sat nav	OK	Steering	OK