



# VEHICLE INSPECTION REPORT

**GY65XZZ**

## Audi Q5 2.0 TDI [190] Quattro S Line Plus 5dr S Tronic

nama  
 GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

### Details

Reg. date	30/11/2015	Colour	WHITE	MOT Due	16/10/2026
Year	2015	VIN	WAUZZZ8R1GA069723	Gearbox	AUTOMATIC
Mileage	102,391 Miles Warranted	Body Style	Estate	Gears	7
Fuel Type	Diesel	Keys	2		

£100 ADDITIONAL FEE Service due

### Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	BUDGET	6.0mm
OSR	PIRELLI	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Front parking sensor
- Rear wiper
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Navigation system
- Service indicator
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Fog Lamp Surround os  
Missing  
Replace



2: Bumper Front  
Cracked  
Over 25mm



3: Number Plate Front  
Broken  
Replace



4: Bumper Front Grill  
Broken  
Replace



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Scratched  
Over 25mm Thru Paint



7: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



8: Door nsf  
Chipped  
Edge Chip



9: Door nsr  
Dented  
With Paint Damage




10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Dented  
With Paint Damage



12: Tailgate  
Scratched  
Up To 25mm Thru Paint



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Wheel osr  
Scratched  
Over 50mm



15: Door osr  
Chipped  
Edge Chip




16: Door osf  
Chipped  
Edge Chip



17: Wheel osf  
Scratched  
Over 50mm



18: Screen Front  
Cracked  
Replace



19: Roof  
Dented  
Over 30mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK