

# VEHICLE INSPECTION REPORT

**LB22XZK**

## BMW 1 Series 118i [136] Sport 5dr Step Auto [Live Cockpit Pro]

nama  
 GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

### Details

Reg. date	11/07/2022	Colour	GREY	MOT Due	10/07/2026
Year	2022	VIN	WBA7K320507L31412	Gearbox	AUTOMATIC
Mileage	46,371 Miles Warranted	Body Style	Hatchback	Gears	7
Fuel Type	Petrol	Keys	2	Doors	5

£90 ADDITIONAL FEE Service overdue

### Tyres

NSF	BUDGET	5.0mm
NSR	PIRELLI	5.0mm
OSF	BUDGET	5.0mm
OSR	PIRELLI	6.0mm
Spare		

### Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5




2: Bumper Front  
Scratched  
25 to 100mm Thru Paint




3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wheel nsf  
Scratched  
Up To 50mm



5: Door nsf  
Chipped  
1 To 5



6: Door nsr  
Chipped  
1 To 5




7: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



8: Door osr  
Poor Previous Repair  
Poor Paint



9: Door osf  
Chipped  
1 To 5



10: Screen Front  
Chipped  
UpTo 10mm



11: Wheel osf  
Scratched  
Over 50mm

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK