

VEHICLE INSPECTION REPORT

GF11ORN

Land Rover Defender XS Station Wagon TDCi

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	24/06/2011	Colour	GREY	MOT Due	24/12/2026
Year	2011	VIN	SALLDHMS7BA406339	Gearbox	MANUAL
Mileage	133,440 Miles Warranted	Body Style	Light 4X4 Utility	Gears	6
Fuel Type	Diesel	Keys	2		

£90 ADDITIONAL FEE

Tyres

NSF	CONTINENTAL	8.0mm
NSR	CONTINENTAL	8.0mm
OSF	CONTINENTAL	8.0mm
OSR	CONTINENTAL	8.0mm
Spare		

Features


- Heated front seat
- Front electric windows
- Radio/CD
- Metallic Paint
- Towbar
- Central locking
- Air conditioning
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Wing nsf
Scratched
Over 25mm Thru Paint



3: Wing nsf
Dented
Over 30mm



4: Sill ns
Dented
With Paint Damage



5: Door nsf
Chipped
1 To 5



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door osr
Scratched
Over 25mm Thru Paint



9: Sill os
Rusted
Over 5mm



10: Door osf
Chipped
1 To 5



11: Wing osf
Dented
Over 30mm



12: Tailgate
Scratched
Rusted



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK