



VEHICLE INSPECTION REPORT

GY16ZDF

Toyota Aygo 1.0 VVT-i X-Cite 2 5dr x-shift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/06/2016	Keys	1	CAP Average	£5,200.00
Year	2016	Service history	Yes	CAP Below	£4,425.00
Mileage	72,549 Miles Warranted	Service documents	Printout	Gearbox	CVT
Fuel Type	Petrol	Last service date	22/04/2025	Gears	5
Colour	BLUE	Last service miles	72,478	Doors	5
VIN	JTDKGNCE80N163471	MOT Due	05/07/2025		
Body Style	Hatchback	CAP Clean	£5,950.00		

£100 ADDITIONAL FEE CLUTCH KIT FITTED 07/05/2025 @ 72523 Last service 22/04/2025 @ 72478 miles (6 SERVICES 4 MAIN DEALER) Gearbox judders

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	SUNNY	3.0mm
OSR	YOKOHAMA	3.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Electric door mirrors
- Front head restraints
- Drivers airbag
- Remote central locking
- Park assist camera
- Auxiliary input socket
- Air conditioning
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Digital radio
- Climate control
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Wing nsf
Scratched
Over 25mm Not Thru Paint


4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



7: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

8: Door osr
Scratched
Over 25mm Not Thru Paint

No Image



9: Door osf
Scratched
Over 25mm Not Thru Paint

10: Sill ns
Dented
With Paint Damage

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK