

VEHICLE INSPECTION REPORT

LK16ZXV

Isuzu Trucks Forward N75.190 Auto 2 car transporter

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	14/03/2016	VIN	JAANPR75MF7101163	Last service date	18/02/2026
Year	2016	Body Style	Car Transporter	Last service miles	363,608
Mileage	363,612 Km Warranted	Keys	2	MOT Due	31/01/2027
Fuel Type	Diesel	Service history	Yes	Gearbox	auto
Colour	WHITE	Number of stamps	20		

Serviced and inspected within operators licence requirements . 2 keys

Tyres

NSF	4.0mm	NSI1	NSI2	4.0mm	NSI3	4.0mm	NSI4	4.0mm
OSF	4.0mm	OSI1	OSI2	4.0mm	OSI3	4.0mm	OSI4	4.0mm
Spare		NSO1	NSO2	4.0mm	NSO3	4.0mm	NSO4	4.0mm
		OSO1	OSO2	4.0mm	OSO3	4.0mm	OSO4	4.0mm

Features

- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door osf
Scratched
Over 25mm Thru Paint



2: Door nsf
Dented
Between 10mm + 30mm



3: Door nsf
Scratched
Over 25mm Not Thru Paint



4: Door nsf
Chipped
1 To 5



5: Bonnet
Rusted
Over 5mm



6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
-

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK