



VEHICLE INSPECTION REPORT

GY22XMS

Vauxhall Corsa 1.2 Turbo SRi 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	20/05/2022	Body Style	Hatchback	Last service miles	66,950
Year	2022	Keys	2	MOT Due	19/05/2026
Mileage	77,906 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	ORANGE	Number of stamps	4	Doors	5
VIN	VXKUPHNEKM4326817	Last service date	13/08/2025		

Last service 13/08/2025 at 66,950 miles- 4 main dealer services. Book Abs light is on
 Collision detection system faulty
 ESP light is on
 Service spanner is displayed

Tyres



NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Service indicator
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Steering wheel mounted controls
- Front fog lights
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear parking sensor
- Digital radio
- Air conditioning
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Flasher Side Repeater ns
Broken
Replace



6: Door nsf
Scratched
UpTo 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Chipped
1 To 5



12: Door osf
Chipped
Edge Chip



13: Wing osf
Chipped
1 To 5



14: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK