



VEHICLE INSPECTION REPORT

GX21HMO

Ford Ranger Pick Up Double Cab Wildtrak 2.0 EcoBlue 213 Auto

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	01/03/2021	Body Style	Pick-up	Last service miles	63,088
Year	2021	Keys	1	MOT Due	01/03/2027
Mileage	89,307 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	1
Colour	GREY	Number of stamps	6		
VIN	6FPPXXMJ2PLK13945	Last service date	05/07/2024		

£100 ADDITIONAL FEE

Last service 05/07/2024 at 63,088 miles- 6 main dealer services. Print Transmission rattle until car is warm

Tyres

NSF	GENERAL TIRE	6.0mm
NSR	GENERAL TIRE	6.0mm
OSF	GENERAL TIRE	6.0mm
OSR	GENERAL TIRE	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Towbar
- Metallic Paint
- Leather seat trim
- Cruise control
- Park assist camera
- Air conditioning
- Drivers airbag
- Front parking sensor
- Rear parking sensor
- Front electric windows
- Passenger airbag
- Heated front seat
- Radio/CD
- Rear electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Tailgate
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Chipped
Edge Chip



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Bumper Front
Scratched
UpTo 25mm Thru Paint



8: Bumper Front
Scratched
Over 25mm Not Thru Paint



9: Bonnet
Chipped
1 To 5



10: Screen Front
Cracked
Replace



11: Door osf
Dented
Over 30mm



12: Door osr
Dented
Over 30mm



13: Bumper Front Moulding
Scratched (Painted)
Up To 25mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK