



VEHICLE INSPECTION REPORT

GY72KFR

Kia Ceed 1.5T GDi ISG 3 5dr

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/09/2022	VIN	U5YH2515LNL167079	Gearbox	MANUAL
Year	2022	Body Style	Hatchback	Gears	6
Mileage	12,431 Miles Warranted	Keys	2	Doors	5
Fuel Type	Petrol	Service history	None		
Colour	WHITE	MOT Due	30/09/2026		

£90 ADDITIONAL FEE.
 No service history

Tyres

NSF	MICHELIN	2.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	2.3mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check




Damage Photos




1: Wheel of
Scratched
Over 50mm




2: Wing of
Chipped
1 To 5




3: Wheel osr
Scratched
Over 50mm




4: Bumper Rear
Scratched
Over 25mm Not Thru Paint




5: Wheel nsr
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Wheel nsf
Scratched
Over 50mm



8: Bumper Front
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK