

VEHICLE INSPECTION REPORT

GF13RFN

Hyundai I10 1.2 Classic 5dr

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	25/06/2013	Body Style	Hatchback	Last service miles	65,640
Year	2013	Keys	2	MOT Due	04/10/2026
Mileage	129,448 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	6	Doors	5
VIN	MALAN51CLEM404758	Last service date	15/05/2018		

Last service 15/05/2018 at 65,640 miles- 6 main dealer services. Book Rear headrests missing
 Abs light on
 Drivers window does not open
 Suspension noise

Tyres

NSF	HIFLY	4.0mm
NSR	FALKEN	4.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- ABS
- Cloth seat trim
- Rear wiper
- Air conditioning
- Drivers airbag
- Steel wheels
- Telephone
- Front electric windows
- Passenger airbag
- Radio/CD
- Solid Paint
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsf
Holed
UpTo 3mm



2: Seat Base Cover osf
Holed
Over 3mm



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Dented
Over 30mm



5: Bumper Rear
Scratched
Over 100mm Thru Paint



6: Tailgate
Chipped
1 To 5



7: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Door nsf
Chipped
Edge Chip



10: Door nsf
Dented
2 Or Less UpTo 10mm



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Bumper Front
Chipped
Multiple Chips



13: Bonnet
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm



15: Door osr
Chipped
1 To 5



16: Door osr
Scratched
UpTo 25mm Thru Paint



17: Carpets Front
Holed
Over 3mm



18: Door nsr
Poor Previous Repair
Paint Flake

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	Fault	Radio	OK
		Steering	OK