



# VEHICLE INSPECTION REPORT

**KX09RKJ**

## Mini Convertible 1.6 Cooper S 2dr Auto

nama  
GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	05/08/2009	Body Style	Convertible	Last service miles	77,996
Year	2009	Keys	2	MOT Due	11/02/2027
Mileage	78,805 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	13		
VIN	WMWMS32070TJ92992	Last service date	29/01/2026		

£90 ADDITIONAL FEE.

last service 29/1/26 @ 77,996 miles (13 services 3 main dealer) book & print

fitted new timing chain tensioner on 19/7/22 @ 53,225 miles Vehicle is burning oil , potential Head Gasket Issue

### Tyres


NSF	PIRELLI	Damaged
NSR	PIRELLI	4.0mm
OSF	PIRELLI	2.5mm
OSR	BRIDGESTONE	4.0mm
Spare		

## Features


- Rear parking sensor
- Electric door mirrors
- Front armrest
- Solid Paint
- Tyre pressure monitor
- Leather seat trim
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Central locking
- Alloy wheels
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Poor Previous Repair  
Poor Paint



3: Qtr Panel osr  
Chipped  
1 To 5



4: Wheel osr  
Scratched  
Over 50mm



5: Wheel nsr  
Scratched  
Over 50mm



6: Door nsf  
Chipped  
Edge Chip



7: Wheel nsf  
Scratched  
Over 50mm



8: Bumper Front  
Chipped  
1 To 5



9: Qtr Panel nsr  
Dented  
Between 10mm + 30mm

10: Tyre nsf  
Damaged  
Replace

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK