

# VEHICLE INSPECTION REPORT

**AV13LBF**

## Renault Traffic SL27dCi 90 [Sat Nav] Van Euro 5

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

nama  
 GRADE  
**4**

### Details

Reg. date	05/08/2013	Colour	WHITE	Service history	None
Year	2013	VIN	VF1FLA0AEDY518675	MOT Due	18/12/2026
Mileage	189,238 Miles Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	Diesel	Keys	2	Gears	6

£100 ADDITIONAL FEE.  
 No service history Noisy steering  
 Service spanner displayed

### Tyres

NSF	RAPID	5.0mm
NSR	HANKOOK	5.0mm
OSF	RAPID	5.0mm
OSR	RAPID	5.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wing nsf  
Chipped  
1 To 5



4: Flasher Side Repeater ns  
Broken  
Replace



5: Door nsf  
Dented  
Over 30mm



6: B Post ns  
Dented  
Between 10mm + 30mm



7: Door nsr  
Dented  
With Paint Damage



8: Door Moulding nsr  
Missing  
Replace



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Lamp nsr  
Broken  
Replace



11: Tailgate  
Dented  
Over 30mm



12: Roof  
Dented  
Over 30mm



13: Lamp osr  
Broken  
Replace



14: Qtr Panel osr  
Dented  
Over 30mm



15: Panel Front  
Dented  
Over 30mm



16: Door osf  
Dented  
Between 10mm + 30mm



17: Wing osf  
Chipped  
1 To 5



18: Seat Back Cover osf  
Torn  
Over 3mm



19: Door Mirror Glass ns  
Missing  
Replace



20: Bumper Rear Moulding  
Broken  
Replace



21: Bumper Reflector nsr  
Broken  
Replace



22: Wheel osf  
Dented  
Over 30mm (Steel)



23: Wheel nsr  
Dented  
Over 30mm (Steel)

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Poor

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	Fault