



VEHICLE INSPECTION REPORT

BT62BNF

Vauxhall Astra 2.0 CDTi 16V ecoFLEX Elite [165] 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/12/2012	Body Style	Hatchback	Last service miles	97,298
Year	2012	Keys	1	MOT Due	16/12/2026
Mileage	110,018 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	10	Doors	5
VIN	WOLPE6ENXDG044414	Last service date	10/07/2024		

£100 ADDITIONAL FEE

Last Service - 10.07.2024 at 97298 miles (10 services)

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Door Mirror Assy of
Scratched (Painted)
Up To 25mm Thru Paint



3: Door osf
Chipped
1 To 5



4: Door osf
Scratched
Over 25mm Not Thru Paint



5: Door osf
Chipped
Edge Chip



6: Door osr
Scratched
Over 25mm Not Thru Paint



7: Door osr
Chipped
1 To 5



8: Qtr Panel osr
Poor Previous Repair
Paint Flake



9: Bumper Rear
Poor Previous Repair
Paint Flake



10: Bumper Rear Moulding
Broken
Replace



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Wheel nsr
Scratched
Over 50mm



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Door nsf
Scratched
Over 25mm Not Thru Paint



15: Wheel nsf
Scratched
Over 50mm



16: Wing nsf
Chipped
1 To 5



17: Bumper Front
Scratched
Over 100mm Thru Paint



18: Bonnet
Chipped
1 To 5



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK