

# VEHICLE INSPECTION REPORT

**GN63VWL**

## Seat Ibiza 1.4 Toca 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	29/09/2013	Body Style	Hatchback	Last service miles	6,785
Year	2013	Keys	2	MOT Due	01/10/2026
Mileage	44,747 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	1	Doors	5
VIN	VSSZZZ6JZER034948	Last service date	07/04/2015		

£90 ADDITIONAL FEE

last service 7/4/15 @ 6785 miles (1 main dealer) book

### Tyres



NSF	BUDGET	4.0mm
NSR	AVON	5.0mm
OSF	BUDGET	3.0mm
OSR	AVON	5.0mm
Spare		

## Features


- Rear parking sensor
- Electric door mirrors
- Solid Paint
- Traction control
- Alloy wheels
- Rear wiper
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Scratched  
Over 25mm Thru Paint



3: Door osr  
Scratched  
UpTo 25mm Not Thru Paint



4: Wheel osr  
Scratched  
Over 50mm



5: Bumper Rear  
Scratched  
Over 100mm Thru Paint



6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Wheel nsr  
Scratched  
Over 50mm



8: Door nsr  
Scratched  
Over 25mm Thru Paint



9: Door nsf  
Scratched  
Over 25mm Not Thru Paint



10: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



11: Wheel nsf  
Scratched  
Over 50mm



12: Bumper Front  
Scratched  
Over 100mm Thru Paint



13: Bonnet  
Chipped  
Multiple Chips

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK