



VEHICLE INSPECTION REPORT

AV17HGJ

Kia Sportage 2.0 CRDi KX-3 5dr Auto

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/03/2017	Body Style	Estate	Last service miles	111,435
Year	2017	Keys	2	MOT Due	23/08/2026
Mileage	118,057 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	8		
VIN	U5YPH813SHL258306	Last service date	29/09/2025		

Last service 29/09/2025 at 111435 miles (8 services (1 main dealer). Book & print.

Tyres



NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Navigation system
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check




Damage Photos




1: Wheel of
Corroded
Light




2: Wing of
Chipped
1 To 5




3: Door osf
Chipped
1 To 5




4: Door osr
Chipped
1 To 5




5: Wheel osr
Corroded
Light




6: Bumper Rear
Chipped
1 To 5




7: Wheel nsr
Corroded
Light




8: Door nsr
Chipped
1 To 5




9: Door nsf
Chipped
1 To 5




10: Wing nsf
Chipped
1 To 5



11: Bumper Front
Chipped
Multiple Chips



12: Bonnet
Chipped
Multiple Chips



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		