

VEHICLE INSPECTION REPORT

GX23HLM

Ford Fiesta 1.0 EcoBoost Hybrid mHEV 125 ST-Line 5dr

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	14/06/2023	Colour	BLUE	Service history	None
Year	2023	VIN	WF0JXXGAHJPD24595	Gearbox	MANUAL
Mileage	17,585 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Hybrid Electric	Keys	2	Doors	5

£90 ADDITIONAL FEE. No service history.

Tyres



NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	Damaged
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check




Damage Photos




1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Chipped
1 To 5




3: Wing nsf
Chipped
1 To 5




4: Wheel nsf
Scratched
Over 50mm




5: Door nsf
Chipped
1 To 5




6: Wheel nsr
Scratched
Over 50mm




7: Door nsr
Scratched
Over 25mm Not Thru Paint




8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint




9: Qtr Panel osr
Scratched
Over 25mm Thru Paint




10: Door osr
Chipped
1 To 5



11: Door osf
Chipped
1 To 5



12: Wheel osf
Scratched
Over 50mm



13: Tyre osf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK