



# VEHICLE INSPECTION REPORT

**VK63DWV**

## BMW 1 Series 118d M Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	18/10/2013	Body Style	Hatchback	Last service miles	113,331
Year	2013	Keys	2	MOT Due	23/10/2026
Mileage	115,190 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	2	Doors	5
VIN	WBA1C12010J090958	Last service date	03/10/2025		

last service 3/10/25 @ 113,331 miles (2 services) print

### Tyres

NSF	BUDGET	5.0mm
NSR	KORMORAN	1.7mm
OSF	BUDGET	5.0mm
OSR	IMPERIAL	2.5mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Wheel of  
Scratched  
Up To 50mm



2: Wing of  
Chipped  
1 To 5



3: Door osf  
Poor Previous Repair  
Poor Paint



4: Wheel osr  
Scratched  
Over 50mm



5: Qtr Panel osr  
Poor Previous Repair  
Poor Paint



6: Door nsr  
Chipped  
1 To 5



7: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Door nsr  
Poor Previous Repair  
Poor Paint



10: Wheel nsf  
Scratched  
Over 50mm



11: Other  
N/A  
N/A



12: Bumper Front  
Poor Previous Repair  
Poor Paint



13: Bonnet  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK