



VEHICLE INSPECTION REPORT

GF10ZBT

Audi A5 2.0T FSI Quattro SE 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	25/05/2010	Body Style	Hatchback	Last service miles	80,580
Year	2010	Keys	2	MOT Due	07/09/2026
Mileage	81,834 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	RED	Number of stamps	10	Doors	5
VIN	WAUZZZ8T0AA081395	Last service date	11/09/2025		

last service 11/9/25 @ 80,580 miles (10 services 3 main dealer) book Service due message displayed
 Knocking rear suspension
 Steering knocking

Tyres

NSF	WESTLAKE	5.0mm
NSR	BUDGET	4.0mm
OSF	GOODYEAR	4.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Navigation system
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos







Condition Check




Damage Photos




1: Wing of
Poor Previous Repair
Poor Paint




2: Wheel of
Scratched
Over 50mm




3: Door osf
Chipped
1 To 5




4: Door osf
Scratched
Over 25mm Not Thru Paint




5: Door osr
Chipped
1 To 5




6: Qtr Panel osr
Chipped
1 To 5




7: Bumper Rear
Scratched
Over 100mm Thru Paint




8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




9: Door nsr
Chipped
1 To 5




10: Door nsf
Chipped
1 To 5




11: Wheel nsf
Scratched
Over 50mm




12: Wing nsf
Scratched
Over 25mm Not Thru Paint



13: Bumper Front
Poor Previous Repair
Paint Flake



14: Bonnet
Poor Previous Repair
Poor Paint



15: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK