



VEHICLE INSPECTION REPORT

OV62UBW

Audi A5 3.0 TDI 204 S Line 2dr Multitronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/01/2013	Body Style	Convertible	Last service miles	84,220
Year	2013	Keys	1	MOT Due	20/05/2026
Mileage	97,884 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	GREY	Number of stamps	5		
VIN	WAUZZZ8F7DN005163	Last service date	27/09/2024		

£90 ADDITIONAL FEE.

Last service 27/09/2024 at 84220 miles (5 main dealer services). Service light on

Tyres

NSF	PIRELLI	4.0mm
NSR	DUNLOP	4.0mm
OSF	PIRELLI	3.0mm
OSR	DUNLOP	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
Over 25mm Not Thru Paint



3: Door osf
Chipped
1 To 5



4: Door osf
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Rusted
Over 5mm



6: Wheel osr
Scratched
Up To 50mm



7: Bumper Rear
Poor Previous Repair
Poor Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Up To 50mm



10: Door nsf
Dented
2 Or Less Up To 10mm



11: Door nsf
Scratched
Over 25mm Not Thru Paint



12: Wing nsf
Dented
With Paint Damage



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		