



VEHICLE INSPECTION REPORT

GU65VDF

Vauxhall Meriva 1.4i 16V Life 5dr

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/09/2015	Body Style	MPV	Last service miles	57,649
Year	2015	Keys	2	MOT Due	14/02/2027
Mileage	60,279 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	9		
VIN	W0LSC9DC0F4173364	Last service date	07/02/2025		

LAST SERVICE - 07/02/2025 @ 57,649 MILES (9 SERVICES, 3 MAIN DEALER)
 BOOK & PRINT EML light on car has been plugged in and detects
 •oxygen sensor circuit high voltage bank 1 sensor 2

Central locking fault

Tyres

NSF	BUDGET	5.0mm
NSR	FALKEN	5.0mm
OSF	RIKEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Dented
2 Or Less UpTo 10mm



3: Door osf
Scratched
Over 25mm Not Thru Paint



4: Tailgate Trim Panel
Broken
Replace



5: Door nsr
Chipped
1 To 5



6: Door nsf
Chipped
Edge Chip



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Wing nsf
Scratched
Over 25mm Not Thru Paint



9: Bumper Front
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK