

# VEHICLE INSPECTION REPORT

**LX06ZDR**

## Nissan Micra 1.2 SE 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
 GRADE  
**4**

### Details

Reg. date	16/04/2006	VIN	SJNEBAK12U2124311	Gearbox	MANUAL
Year	2006	Body Style	Hatchback	Gears	5
Mileage	69,678 Miles Warranted	Keys	2	Doors	3
Fuel Type	Petrol	Service history	None		
Colour	GREY	MOT Due	23/07/2026		

£65 ADDITIONAL FEE.

No Service History Boot does not open

### Tyres

NSF	SAILUN	3.0mm
NSR	SAILUN	4.0mm
OSF	SAILUN	3.0mm
OSR	SAILUN	5.0mm
Spare		

## Features


- Rear wiper
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Steel wheels
- Electric door mirrors
- Metallic Paint
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Wing osf  
Dented  
2 Or Less UpTo 10mm



3: Door osf  
Chipped  
Multiple Chips



4: Other  
N/A  
N/A



5: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



6: Qtr Panel osr  
Chipped  
1 To 5



7: Bumper Rear  
Scratched  
Over 100mm Thru Paint



8: Other  
N/A  
N/A



9: Other  
N/A  
N/A



10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Door nsf  
Scratched  
Over 25mm Thru Paint




12: Wing nsf  
Dented  
With Paint Damage



13: Bumper Front  
Scratched  
25 to 100mm Thru Paint



14: Bonnet  
Dented  
With Paint Damage



15: Roof  
Dented  
2 Or Less UpTo 10mm



16: Door Pad nsf  
Missing  
Replace



17: Door Pad osf  
Missing  
Replace

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK