



# VEHICLE INSPECTION REPORT

**GL19PBY**

## HYUNDAI TUCSON 1.6 CRDi 136 Premium 5dr 2WD DCT

**Inspection**

**Vehicle**

VAT	Margin
V5	TBC

**Details**

<b>Reg. date</b>	29/03/2019	<b>Colour</b>	BLACK	<b>Gearbox</b>	SEMI AUTO
<b>Year</b>	2019	<b>VIN</b>	TMAJ3817VKJ725309	<b>Gears</b>	7
<b>Mileage</b>	57,000 Miles Warranted	<b>Body Style</b>	Estate		
<b>Fuel Type</b>	Diesel	<b>MOT Due</b>	14/05/2026		

£90 ADDITIONAL FEE.

**Tyres**

<b>NSF</b>
<b>NSR</b>
<b>OSF</b>
<b>OSR</b>
<b>Spare</b>