



# VEHICLE INSPECTION REPORT

**KV12WBE**

## Nissan Qashqai 1.6 [117] N-Tec 5dr

nama  
GRADE  
**4**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	14/03/2012	Body Style	Hatchback	Last service miles	75,288
Year	2012	Keys	2	MOT Due	24/03/2027
Mileage	105,117 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	5	Doors	5
VIN	SJNFAAJ10U2505973	Last service date	17/03/2020		

Last service 17/03/2020 at 75,288 miles- 5 services. Book SD card missing for sat nav  
 Heath shield rattling

### Tyres

NSF	BUDGET	5.0mm
NSR	ZEETEX	5.0mm
OSF	BUDGET	5.0mm
OSR	ZEETEX	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Digital radio
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsr  
Dented  
With Paint Damage



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Bumper Rear  
Dented  
With Paint Damage



10: Lamp nsr  
Broken  
Replace



11: Wheel osr  
Scratched  
Over 50mm



12: Door nsr  
Scratched  
Over 25mm Thru Paint



13: Door osf  
Dented  
Over 30mm



14: Wing osf  
Dented  
Over 30mm



15: Wheel osf  
Scratched  
Over 50mm



16: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK