



VEHICLE INSPECTION REPORT

GX63ZXB

Nissan Qashqai 2.0 dCi Tekna 5dr Auto 4WD

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	20/09/2013	Body Style	Hatchback	Last service miles	82,367
Year	2013	Keys	2	MOT Due	22/09/2026
Mileage	87,604 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	10	Doors	5
VIN	SJNFDNJ10U2870994	Last service date	03/09/2025		

Last Service -03.09.2025 at 82367 miles (10 services) NOISY GEARBOX

Tyres

NSF	WESTLAKE	5.0mm
NSR	WESTLAKE	5.0mm
OSF	WESTLAKE	4.0mm
OSR	WESTLAKE	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel of
Corroded
Light



2: Door Mirror Assy of
Scratched (Painted)
Over 25mm Thru Paint



3: Door osf
Chipped
Edge Chip



4: Door osr
Dented
Between 10mm + 30mm



5: Qtr Panel osr
Poor Previous Repair
Poor Paint



6: Wheel nsr
Corroded
Light



7: Door nsr
Chipped
1 To 5



8: Door nsf
Chipped
1 To 5



9: Wing nsf
Poor Previous Repair
Paint Flake



10: Wheel nsf
Corroded
Light



11: Bonnet
Chipped
1 To 5



12: Bumper Front
Scratched
Over 25mm Not Thru Paint



13: Bumper Front
Chipped
Multiple Chips



14: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		