

VEHICLE INSPECTION REPORT

HN60KKB

Kia Picanto 1.1 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	05/11/2010	Body Style	Hatchback	Last service miles	119,500
Year	2010	Keys	2	MOT Due	05/11/2026
Mileage	121,859 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	13	Doors	5
VIN	KNABJ513LBT059982	Last service date	13/10/2025		

£50 ADDITIONAL FEE

Last Service - 13.10.2025 at 119500 miles (13 services) Duel controls fitted


Tyres

NSF	SUNNY	4.0mm
NSR	BUDGET	4.0mm
OSF	SUNNY	4.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Rear wiper
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Rear headrests
- Passenger airbag
- Steel wheels
- Body coloured bumpers
- Solid Paint
- Central locking
- Air conditioning
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Paint Flake



2: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Door osr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



7: Tailgate
Poor Previous Repair
Paint Flake



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Other
N/A
N/A



10: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



11: Wing nsf
Scratched
Over 25mm Not Thru Paint



12: Bumper Front
Scratched
Over 25mm Not Thru Paint



13: Bonnet
Chipped
Multiple Chips

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK