

# VEHICLE INSPECTION REPORT

**AV65GDE**

## Volkswagen Golf Sv 1.4 TSI SE 5dr DSG

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	28/09/2015	Body Style	MPV	Last service miles	147,464
Year	2015	Keys	1	MOT Due	06/10/2026
Mileage	150,000 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	SILVER	Number of stamps	13		
VIN	WVVZZZAUZGW532412	Last service date	08/01/2026		

£100 ADDITIONAL FEE

Last Service - 08.01.2026 at 147464 miles (13 main dealer services)

### Tyres

NSF	YOKOHAMA	2.0mm
NSR	AVON	4.0mm
OSF	YOKOHAMA	2.0mm
OSR	AVON	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Corroded  
Light



2: Door osf  
Chipped  
1 To 5



3: Qtr Panel osr  
Dented  
With Paint Damage



4: Wheel osr  
Corroded  
Light



5: Bumper Rear  
Scratched  
Over 100mm Thru Paint



6: Qtr Panel nsr  
Dented  
Over 30mm



7: Wheel nsr  
Corroded  
Light



8: Door nsr  
Chipped  
1 To 5



9: Door nsf  
Chipped  
1 To 5



10: Wheel nsf  
Corroded  
Light



11: Bonnet  
Chipped  
1 To 5

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK