

VEHICLE INSPECTION REPORT

RO61GBZ

Volkswagen Golf 1.6 TDi 105 BlueMotion Tech Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	29/09/2011	Body Style	Hatchback	Last service miles	114,909
Year	2011	Keys	2	MOT Due	31/07/2026
Mileage	120,375 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	10	Doors	5
VIN	WVVZZZ1KZCW091596	Last service date	21/07/2025		

LAST SERVICE 21/07/2025 @ 114,909 MILES (10 SERVICES) Clutch pedal clicks

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osr
Scratched
UpTo 25mm Thru Paint



4: Door osr
Chipped
Edge Chip



5: Wheel osr
Scratched
Over 50mm



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



9: Qtr Panel nsf
Chipped
1 To 5



10: Door nsf
Scratched
UpTo 25mm Not Thru Paint



11: Door nsf
Chipped
1 To 5



12: Wing nsf
Scratched
Over 25mm Thru Paint



13: Wheel nsf
Scratched
Over 50mm



14: Bonnet
Chipped
Multiple Chips



15: Bumper Front
Chipped
Multiple Chips



16: A Post os
Chipped
1 To 5



17: Roof
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK